# Install Guide for OPTIR Touch Screen Overlay
## with Glass and Custom Mount

1. Carefully remove side Velcro (hook) strips. Leave the Velcro (loop) strips on the touch overlay.

2. The Velcro (hook) can be added to the left, right, and bottom sides of the monitor's front bezel. For thin bezel monitors, the Velcro may wrap around the sides and to the back.

3. Align frame to the monitor so that the display area matches closely with the open touch area of the touch screen. The mounting bar should rest on top of the upright monitor.

4. Once aligned, press the touch screen firmly into place and plug in the USB cable to the PC's empty USB port.